Environmental and Analytical Services-Since 1994 California State Accredited Laboratory in Accordance with ELAP Certificate # 2332

Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: October 7, 2016

Laboratory Number: 162224

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Ken Hindman

Enclosed are the analysis results for samples received October 3, 2016 with the Chain of Custody document. The sample was received in good condition, at 6° C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

162224-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.



Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 162224

Analyst: AV

Date Sampled: 10/03/16

Date Received: 10/03/16 Date Analyzed: 10/04/16

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
162224-01	Produced Water	6 . 0	1	1.0	5.0

QUALITY CONTROL REPORT

162224-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit
ND: Not Detected or <MDL value</pre>

												•	4	\$	75	≱								
	T	Verified by Lead Operator:(Signature)	Print Name: 1 Conopolo	Ralinquished by :(Sign	Print Name: MARCI	Relinquished by :(Si							1 10/3	Sample Date NO. Sampled	Print Name: スドン	SAMPLER'S SIGNATURE		PHOD. NO.		CHAIN OF CUSTODY RECORD	(805) 644-1095 Fax 644-9947	Ventura, CA 93003	SERVICES 1536 Eastman Avenue	CAPCO ANALYTICAL
	Print Name:	ad Operator:(S		ature)		by :(Signature)							06:00	Time Comp	ANDANA S	None Park				TODY RECOF	Fax 644-9947)OG -	Wenue	ANALYTICAL
		ignature)	1235 1235	שן -3 ימו חן -3 ימו	Time 7:00	Date 10:3:11							×	np Grab	5		rced Wa	Hillhouse		õ				
	Time	Date	Print Name:	Received by :(Signature)	Cright Name:	Required by Signature	-)						Produced Water	Sample Description			Produced Water- Weekly	USO NAME:	Phone: 805 535-2078		Address	Company	Fax	
			MINSTITE		Havius								×	Water Soil Studge Other	Matrix	A=Amber Bottle, G=C P=Plastic, V=Vial, O=Other	CONTAINER TYPES		Contact: Jay Rao	Ventura CA. 93003	290 Maple Court. Suite 290	DCOR,LLC.	(805) 535-2075	
48Hr	24Hr.		Print Name:	Relinquist	PrintName								A	Container # Type	Δ.	ther aly				Ö		လ	P,0.#	<u> </u>
			<u>е</u> :	Signaturé)	ame: O TOUL	and by: Signative)			,			×	C		& Gr)			Address	Company:	P.O. #	<u>-</u>
Standard X	5 day	Turn Around time	Time	Date	T & Fine C	10/2/p																DCOR,LLC.		
		Φ	Print Name:	Received by :(Signature)	Why Leonar do	Received by (Signature)	Return samples	CHECK ONE BOX				Turbidity: NTU 3.08	Produced Water Temp: 80	Remarks			0 5,							ゴッシン

Pte D

B



Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: October 13, 2016

Laboratory Number: 162270

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Jeff Maser

Enclosed are the analysis results for samples received October 10, 2016 with the Chain of Custody document. The sample was received in good condition, at 8° C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

162270-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.



Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 162270

Analyst: AV

Date Sampled: 10/10/16
Date Received: 10/10/16

Date Analyzed: 10/11/16

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
162270-01	Produced Water	2.6J*	1	1.0	5.0

QUALITY CONTROL REPORT

162270-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

	Standard X other		48Hr 72Hr						
	5 day		24Hr.			0700	Olbertsan	DOE 1916	15
O.	urn Around time	Ти				10-10-16	Lead Operator:(Signature)	red by Lead O	
Print Name:	Time	ame:	Print Name:	CIA	VETTSKIN	-	Ow III	Lland Lanapolu	Llouc
Received by :(Signature)	Date	Helinquished by (Signature)	Helinqu	"	-	neceived by (Samature)	<u> </u>	Siled by (Oighamle)	
Lind Lonandu	F. O.O	the two watch	Print	letry	03	AR TURO	0760	LI /2 '	John Mark
	10~10-16	Helinquished by :(Signature)	Helinqu			neceived by (oignature)	10-10-16	De Oldodas	8
Return samples			7					2	Reling
Dispose samples									
Turbidity: NTU 3,46									
Produced Water Temp: 79"		×	٦ A			Produced Water	X	110-1016 C	-
Remarks		0	Container # Type	Sludge	Water Soil	Sample Description	Time Sampled Comp Grab	Date Sampled	Sample NO.
				Matrix			LE WYSEK	ame: TEF	Print Name:
		Gre	G≂Glass,)ther	A=Amber Bottle, G=C P=Plastic, V=Vial, O=Other	A=Amber P=Plastic, V:		5 Maan	SAMPLER'S SIGNATURE:	SAMP
5 7 3 3			YPES	CONTAINER TYPES	င္တဲ့	ater- Weekly	1 22		
10/12		e	,)USE	Hillhouse	PHOJ. NO.	7
				Contact: Jay Rao	Contact:	805 535-2078			2
				Ventura CA, 93003	Ver		DY RECORD	CHAIN OF CUSTODY RECORD	CHAI
		Address		290 Maple Court. Suite 290	290 N	Address	644-9947	(805) 644-1095 Fax 644-9947	(805)
	DCOR,LLC.	Company:		DCOR,LLC.		Company		Ventura, CA 93003	Ventu
		P.O. #		(805) 535-2075		Fax	IUe	SERVICES 1536 Eastman Avenue	1536
							ALYTICAL	CAPCO ANALYTICAL	CA



Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: October 21, 2016

Laboratory Number: 162309

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: David Hart

Enclosed are the analysis results for samples received October 18, 2016 with the Chain of Custody document. The sample was received in good condition, at 6°C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

162309-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory\Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.



Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 162309

Analyst: AV

Date Sampled: 10/17/16

Date Received: 10/18/16 Date Analyzed: 10/18/16

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
162309-01	Produced Water	2.5J*	1	1.0	5.0

QUALITY CONTROL REPORT

162309-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

B SAMPLER'S SIGNATURE: 1536 Eastman Avenue Ventura, CA 93003 Print Name: VAVIO HART **CHAIN OF CUSTODY RECORD** (805) 644-1095 Fax 644-9947 SERVICES Print Name: 1040 L POVIADO CAPCO ANALYTICAL Verified by Lead Operator: (Signature) Ö KEY HINDWAY Sampled Sampled 10-17-16 06:30 Date Print Name: ime **Produced Water- Weekly** Comp 01:00 04-91- **d** 10-18-16 10 350 Time Time Date PROJECT NAME: Hillhouse Grab REPORT: Phone: 805 535-2078 Produced Water Description Company Sample Address Fax Date Time Lame A=Amber Bottle, G=Glass, P=Plastic, V=Vial, O=Other Contact: Jay Rao ×|_{Water} Régalla 290 Maple Court. Suite 290 CONTAINER TYPES Ventura CA. 93003 Soil DCOR,LLC. (805) 535-2075 Matrix Other 48Hr 72Hr 24Hr Type Print Name: 12 13 15 E Relinquished by :(Signature) P.O. # Address Company: BILL TO: Analysis Oil & Grease d Turn Around time 8-000 ave 10-18-2016 DCOR,LLC. , 5 day Standard other Time Time Produced Water Temp: Turbidity: 4,12 NTU Print Name: Print Name: LOVPLOW Dispose samples Received by :(Signature) Return samples 52309 CHECK ONE BOX Remarks

B

PIC D



Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: October 27, 2016

Laboratory Number: 162345

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Mark Hicks

Enclosed are the analysis results for samples received October 24, 2016 with the Chain of Custody document. The sample was received in good condition, at 8°C, and it was identified and assigned the laboratory ID number listed below.

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

162345-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.



Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 162345

Analyst: AV

Date Sampled: 10/24/16 Date Received: 10/24/16

Date Analyzed: 10/25/16

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
162345-01	Produced Water	 2.3J*	1	1.0	5.0

QUALITY CONTROL REPORT

162345-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

1536 Eastman Avenue Ventura, CA 93003 (805) 644-1095 Fax 644-9947 CHAIN OF CUSTODY RECORD SAMPLER'S SIGNATUBÉ: SERVICES Print Name: CAPCO ANALYTICAL Sample NO. De Alberta reinquisped by (Signature) Verified by Lead Operator:(Signature) Hotel Broken PROJ. NO. 10/24/16 Sampled Sampled Date Joe Albertson Contar Mark Hicks lbetter 06:30 Time Produced Water/ Weekly | 10 -2-1 -12 Comp 91-12-191 0700 Time Date PROJECT NAME: Hillhouse, Grab Received by :(Signature REPORT: Phone: 805 535-2078 Print Name: Produced Water 10-24-16 Time Description 0700 Company Sample Address Date Fax ₹ Signature Xorx CONTAINER TYPES

A=Amber Bottle, G=Glass,
P=Plastic, V=Vial, O=Other Contact: Jay Rao Water 6011 DCOR,LLC. 290 Maple Court. Suite 290 Ventura CA. 93003 MXSKIN Soil (805) 535-2075 \? ? Matrix Other 48Hr 72Hr 24Hr. Relinquished tly:(Signature) Type Print Name elinquished by :(Signat nt Name: どろん P.O. # Address Company: BILL TO: Analysis Oil & Grease となっての Turn Around time 10/2d/16 Time 8',00 DCOR,LLC. Standard 5 day other Date Time Produced Water Temp: Print Name: Hoyonog Lyonow Dispose samples Turbidity: Return samples 52345 CHECK ONE BOX NTU 3.78

ĝ.

Environmental and Analytical Services-Since 1994 California State Accredited Laboratory in Accordance with ELAP Certificate # 2332

Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: November 2, 2016

Laboratory Number: 162391

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Ken Hindman

Enclosed are the analysis results for samples received October 31, 2016 with the Chain of Custody document. The sample was received in good condition, at 10° C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

162391-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

This report shall not be reproduced except in full without the written approval of CAS. The test results reported represent only the item being tested and may not represent the entire material from which the sample was taken.



Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 162391

Analyst: AV

Date Sampled: 10/31/16 Date Received: 10/31/16

Date Analyzed: 11/01/16

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
162391-01	Produced Water	1.2J*	1	1.0	5.0

QUALITY CONTROL REPORT

162391-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

SAMPLER'S SIGNATURE: Print Name: 大丸八 1536 Eastman Avenue Ventura, CA 93003 SERVICES Print Name: 12 (Popopodo CHAIN OF CUSTODY RECORD (805) 644-1095 Fax 644-9947 Helinquished by CAPCO ANALYTICAL Verified by Lead Operator:(Signature) int Name: Trapil Cive bruce PROJ. NO. Date Time Sampled Sampled 10-31-16 06:30 y :(Signature) Print Name: HINDMAN Produced Water- Weekly 07:00 G Time ما ا**3،** Comp જ1−1 દ⊶αι ^{gate} Time PROJECT NAME: Hillhouse Grab × REPORT: Print Name: Received by :(Signature) Received by :(Signature) Description Produced Water A PURIO Sample Company Address Date ax Time 895 A=Amber Bottle, G=Glass P=Plastic, V=Vial, O=Other Contact: Jay Rao \times |Water MINCHAM CONTAINER TYPES 290 Maple Court. Suite 290 Ventura CA. 93003 Soil (805) 535-2075 DCOR,LLC. Sludge Other Container 48Hr 72Hr 24Hr. Type Relinquished by :(Signature) Print Name Relinquished by :(Signature) Print Name: APTURO Þ P.O.# Address Company: BILL TO: Analysis Oil & Grease Turn Around time T. OO AW 10-31-16 Standard DCOR,LLC. 5 day other Time Date Time Print Name: Lloyd Leonapoli Print Name: Received by :(Signature Dispose samples Turbidity: 3.76 NTU Produced Water Temp: 80 Received by Signature) Return samples CHECK ONE BOX Remarks **".** (0

FTC DE